



KEYKEG SAFETY WARNINGS




Depressurize immediately after use.



Working pressure max. 3,5 bar (51 psi)



Keep away from direct sunlight



In case of CO₂ use: do not depressurize in a confined space. Danger of suffocation.

WARNING


- read carefully before use • one-way keg under pressure
- handle with care • professional use only • do not reuse
- storage - keep below 40°C



Keep away from cleaning agents as alkaline, caustic hydroxides or soapy cleaning products with pH > 9.



Do not pierce or cut with sharp objects



Do not roll



Keep away from open fire or other heat sources.